TC77ex-NI Touch Computer

Accessories

It is absolutely necessary to use original accessories from BARTEC!

Accessories for use in hazardous areas

Accessories are approved for:

- ATEX: Zone 2/22 (EPS 17 ATEX 1 028 X)
- IECEx: Zone 2/22 (IECEx EPS 17.0012X)
- NEC: Class I,II, III Div 2 (ETL File 5012876)
- UKEX: Zone 2/22 (CML 21 UKEX2341X)

Battery

Description	– certified in combination with TC77ex-NI – Lithium-ion battery 3.7 V/4620 mAh May only be changed and charged outside hazardous areas!
Order no.	B7-A2Z0-0072

Scan handle

Description	– Certified in combination with TC7x series – Simple assembly and disassembly without tools – Camera and expansion interface remain usable – Hand strap can remain on the device – Holder for stylus – Charging with mounted scan handle in base station not possible, only in the charging station Must be changed only outside hazardous areas!
Order no.	B7-A2Z0-0052

Leather holster

Description	– certified in combination with TC7x series – Holder for stylus
Order no.	B7-A2Z0-0057

Leather carry case

Description	– certified in combination with TC7x series – Robust leather in industrial quality – Holder for stylus – Included belt clip – cannot be used with Scan handle May only be changed outside hazardous areas!
Order no.	B7-A2Z0-0073

Screen protector

Description	– Certified in combination with TC7x series – 1 piece May only be changed outside hazardous areas!
Order no.	B7-A2Z0-0051

Stylus

Description	– Suitable for TC77ex-NI – passive stylus – with spiral cable – 3 pieces May only be changed outside hazardous areas!
Order no.	17-S1Z0-0008

Accessories for use outside hazardous areas

4-slot battery charging station

Description	– Charging four batteries – Charging display via LED
Also required	(not included in the delivery) – Power supply with DC connecting cable – AC power cable
Order no.	G7-A0Z0-0020

Base station

Description	– Charging the Touch Computer (only possible without scan handle) – Charging a spare battery – Data communication 1x USB 1x Ethernet
Also required	(not included in the delivery) – Power supply with DC connecting cable – AC power cable – Micro USB cable for data synchronization
Order no.	G7-A0Z0-0022

Charging station

Description	– Charging the Touch Computer (also possible with scan handle) – Charging a spare battery
Also required	(not included in the delivery) – Power supply with DC connecting cable – AC power cable
Order no.	G7-A0Z0-0048

USB adapter cable

Description	– Charging the Touch Computer – Data synchronization via USB
Also required	(not included in the delivery) – Power supply for USB adapter cable – AC power cable
Order no.	G7-A0Z0-0037

Power supply

Description	– with DC connecting cable – for 4-slot battery charging station and base station – Input voltage: AC 100 V to 240 V – Output voltage: DC 12 V/4,16 A/50 W
Order no.	G7-A0Z0-0023

Power supply

Description	– for USB adapter cable – Including DC connecting cable – Input voltage: AC 100 V to 240 V – Output voltage: DC 5.4 V/3 A/16 W
Order no.	G7-A0Z0-0038

Micro USB cable

Description	– Connection between Touch Computer and base station for data communication – USB (A) to micro USB (B) – Length: 1 m
Order no.	03-9919-0013

AC power cable

Description	– suitable for power supply with DC connection cable – 3-wire – country-specific	
Order no.	US + Canada	G7-A0Z0-0024
	EU + APAC	G7-A0Z0-0026
	Taiwan	G7-A0Z0-0027
	Please purchase the required country-specific cables in the respective country!	

AC power cable

Description	– suitable for power supply for USB adapter cable – 3-wire – country-specific	
Order no.	US + Canada	G7-A0Z0-0032
	EU + APAC	G7-A0Z0-0034
	Please purchase the required country-specific cables in the respective country!	